

WORKS DONE ON THE BOAT ELAN POWER 42 HT

Year 2014:

- Installation Raymarine Radar 24 NM (€ 1,350.00)
- Installation IR camera in the engine room with monitors on the consolle of the comands (€ 300.00)
- Installation additional mt. 50 Chain 8 mm. , change stemhead (€ 600.00)
- Installation cameras in the cockpit and inside the boat (€ 1,250.00)
- Installation of the 2nd plotter NAVSTATION Suncolor 6 " and GPS antenna (€ 650.00)
- Installation 2nd sounder Lowrance Elite (€ 850.00)
- Dimming 50% of the cockpit with application of heat reflective film on all windows of the cockpit (€ 5,200.00).
- Installation "whistle" approved (€ 380.00)
- Installation searchlight (€ 410.00)
- Installation of the AIS unit connected to the plotter 8 "(€ 400.00)
- Installation LED headlight stern for the mooring in the night (€ 200.00)

Year 2015:

- RINA certification updated (valid until year 2020) (€ 900.00)
- Polishing hull (€ 1,600.00)
- Application of wrapping side in metallic grey and imitation leather on furniture cockpit (€ 700.00)
- Replacing both propellers VOLVO (€ 4,800.00)
- Installation "Jet Thruster" JT50 of Hollandmarine (www.hollandmarineparts.nl) complete with n. 2 batteries Optima Yellow translational stern (€ 7,800.00)
- Installation double autoclave with circuits sectioned (€ 550.00)
- Installation electric winch wireless controll with meter counter (€ 380.00)
- Installation new batteries (n. 2x 148Ah - n. 2x180 Ah) (€ 750.00)
- Replacing n. 5 covers of mattresses (€ 500.00)
- Installation new taps (€ 450.00)
- Replacing cloth of the opening top (€ 350.00)
- Installation underwater lights led at stern (€ 900.00)
- Installation 2 DVD players in the cabins (€ 250.00)

Service done every year, change of the impellers of the engines every year, change of the impeller of the generator every year.